## Nº 6895 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-20-3	FIRST MANHOLE DOWN STREAM
HOUSE NO. 569	
SIZE OF PIPE USED//	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB?	andronia de la companya de la compa ➡
WAS ATTACHED TO MAIN VES	- NAME OF CONTRACTOR June / June
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.
	12
W	76
. 1	12' 40
SIGNED POTI Parti	FILED AT ENGINEER'S OFFICE 9-18-59
REMARKS	
· · · · · · · · · · · · · · · · ·	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 6895 PERMIT TO TAP SEWER

MASSILLON, OHIO, 15 19
RECEIVED OF THE FEE OF \$ 2 C
FOR WHICH PERMISSION IS GRANTED M. A. Builders
TO TAPSEWER ON THE
OF CARING WILL ST. TYPE OF STREET
THE PREMISES BEING LOT NO. 12 MAIN ALANGE THE PREMISES BEING LOT NO. 12 MAIN ALANGE THE HOUSE NO. 579
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL.
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR ME & DE

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.