## Nº \_6896

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-19-58 IF SO HOW AND LOCATION FROM 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
HOUSE NO
SIZE OF PIPE USED DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB? VO
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR - Sof Y John
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
N 7'0
22' VHD 102'
SIGNED Roy Lathorn FILED AT ENGINEER'S OFFICE 9-18-58
/ INSPECTOR FOR CITY
REMARKS

## Nº 6896

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, ///1./5 19.
RECEIVED OF THE Y THE STEE OF \$ 5 -
FOR WHICH PERMISSION IS GRANTED 4 1 Quelders
TO TAP SEWER ON THE
OF Carres 7.11. AVE. ST. TYPE OF STREET.
THE PREMISES BEING LOT NO. 13 Mail flaure, 4. House No. 575
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
Name of Contractor

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.