## Nº 6916

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-9-5-5	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 905		
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	<u> </u>
WAS LATERAL AT CURB? YES	of the second	*
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR P. P. L.	nley
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
	16/1	
and the second s	and the same of th	50 0
	N	
tion de la particular de la completa de la completa La completa de la co		
	1'-16-6.0	
	9184	deministration of the second state of the seco
SIGNED Rol Kathan	FILED AT ENGINEER'S OFFICE	81'
INSPECTOR FOR CIT		
REMARKS		

7-16

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 6916

PERMIT TO TAP SEWER

	0	0	MASSILL	ON, OHIO,	70	1
RECEIVED OF	$f_{ij}$	1) 11 -	10 Du 1-		FE	E OF \$
FOR WHICH PERMISSI	ON IS GRANTE			0 - 2		
TO TAP	Marie I.		SEWER ON TH	E UL		
OF 0 +1	J. Harry	/ AVE	E. . Type of Stri	BET >	. 0	Die I
THE PREMISES BEING		140	<u></u>	, HOUSE NO,_		7
THE PREMISES SEINS					/ 1	
WORK TO BE DONE I	N ACCORDAN	CE WITH OR	DINANCE NO.	2323, DULY PA	SED BY THE	CITY COUNC

ME OF CONTRACTOR Land

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.