Nº 6917 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-10-5-8	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH A CYOSS FYOTT MAN 7
WAS LATERAL AT CURBY YES	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Rembel
SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SERVED,
	6' 3'deep
	- 170,
SIGNED ROY INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE
REMARKS	

3-4/

14 of the director of public service of the director of public service PERMIT TO TAP SEWER

ا.		ing the later grade the state of the state o	assillon, Ohio,	9/8
	RECEIVED OF	RR	a t	FEE OF 5
FOR	WHICH PERMISSION IS G	RANTED	Mount.	رمير
тот	TAP	SEWER	ON THE	
OF_	(6" 0)	AVE. TYPE O	F STREET	<u>a l</u>
THE	PREMISES BEING LOT NO	, 40 to	, HOUSE NO	1314

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR TO THE CONTRACTOR

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.