

No. 6922

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED

9-23-58

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

431

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?

NO

WAS ATTACHED TO MAIN


NO

NAME OF CONTRACTOR

H. URBAN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N



SIGNED

William E. White
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10-27-58

12-8-58

REMARKS

LINE WAS NOT IN YET

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 6922

PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/17 1917RECEIVED OF Harvey L. Leland

FEE OF \$

FOR WHICH PERMISSION IS GRANTED John D. LelandTO TAP SanSEWER ON THE 60OF 2571 7th

AVE.

ST. TYPE OF STREET WestTHE PREMISES BEING LOT NO. 7067HOUSE NO. 1131

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H. Leland

Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.