Nº 6932

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-2-58	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	*
HOUSE NO. 1/04		
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH ### ### ############################	EAM MY. 7 = D
WAS LATERAL AT CURB? YES	and a substantial control of the state of the	· · · · · · · · · · · · · · · · · · ·
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR H.J. DIANH	
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.	
rafir ang grant dan d anag ilik alipunan dan dari s	60	
	N 43 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	
Great to the entropy of a case or state from	and the state of t	
	750	
	- 10 510	UPSTREAM MH-
SIGNED Millians C. White	82'	10-29-
/ INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE	10-0)

Nº 6932

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF PERMISSION IS GRANTED	E OF \$ 2
FOR WHICH PERMISSION IS GRANTED	
TO TAP SEWER ON THE	
OF TEARL A E. ST. TYPE OF STREET PARK A	205 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
THE PREMISES BEING LOT NO. 538/ HOUSE NO.	4
THE PREMISES BEING LOT NO	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI

NAME OF CONTRACTOR A. J. Miles

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.