Nº 6938

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	1997年,1997年,1997年,1997年,1997年,1997年,1997年,1997年,1997年,1997年,1997年,1997年,1997年,1997年,1997年,1997年,1997年,1997年,19
DATE INSPECTED 10-78-58	IF SO HOW AND LOCATION FROM
	FIRST MANHOLE DOWN STREAM
HOUSE NO	
HOUSE NO.	
	DOWN STREAM TO DITCH AT
SIZE OF PIPE USED	CURB LINE AND DEPTH / NOT
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN ///	NAME OF CONTRACTOR PRember
SHOW BY DIAGRAM RELATION OF LATE	
ang talah di kacamatan permanangan berasah kebagai dan di bergeren di bangan belang di Kebagai banda. Permanan Bangan berasah di berasah dan permanangan berasah di bangan berasah di bangan berasah berasah berasah berasah	L'oeek in
y jednog kalendarije na jednika 1986. Bili da komence	or and the communication and the contract of t
	v = v + v + v + v + v + v + v + v + v +
Rolling	
SIGNED / O / INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE 12-8-58
AND THE RESERVE OF THE PARTY OF	
REMARKS	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6938

## PERMIT TO TAP SEWER

	Massillon, Ohio, /0/2/ 195
	RECEIVED OF PEE OF \$ 2
٧.	
	TO TAPSEWER ON THE
	OF 25 Th ) W AVE. TYPE OF STREET AAA
	THE PREMISES BEING LOT NO.
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,
	NAME OF CONTRACTOR

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.