

Nº 6943

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-23-58

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 422

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

14'

8' Deep



WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

R REMLEY

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

12-8-58

REMARKS

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6943

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/22 1922

RECEIVED OF Raymond Reuley FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Euther Karness

TO TAP San SEWER ON THE East

OF 25TH N. W. AVE. ST. TYPE OF STREET dist

THE PREMISES BEING LOT NO. 786, HOUSE NO. 122

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Raymond Reuley

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.