FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 18-24-58	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	32' 6'D	
WAS LATERAL AT CURB? YES	o transfer di	a jednada si a storovnarace.	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR H	URBAN	
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SE	RVED.	
SIGNED William E 18 INSPECTOR FOR CI		igineer's office	10-29 -58

Nº 6945

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		. Najema selaki Kumanan jepan	Mas	SILLON, OHIO	, 10/	3	19.
Rec	EIVED OF	Hour	- Mil			FEE OF !	
FOR WILLEL	l PERMISSION IS GR	4		21.6			
TO TAP			SEWER O	N THE	240	<u> </u>	
OF	15 34 1		AVE. _ ST. TYPE OF		der	100 10 10 10 T	
THE PREMI	SES BEING LOT NO.	-	1-02			106	
	BE DONE IN ACCO						Council
· 1	THE DEPARTMENT	and the state of the state of	医多类性病 医二氯苯二 克里达				
NAME OF C	CONTRACTOR	Harre	Mel				

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.