## $N^{0}$ 6955

REMARKS

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

The state of the s	the contract of the contract o	· · · · · · · · · · · · · · · · · · ·	the state of the s
DATE INSPECTED //-//-	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 601	THE WANTED BOWN STREAM		
SIZE OF PIPE USED /// U	DISTANCE FROM FIRST MANHOLE. DISTANCE FROM FIRST MANHOLE. CURB LINE AND DEPTH		1 place
WAS LATERAL AT CURB? V - S	a di la comitato di terrese pede terrese La comitato di terrese	un de explores. Teloposis de la composición del composición de la composición de la composición de la composición de la composición del composición de la composición del composición de la composición del composición del composic	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	R. MAR	2/15
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SE	RVED.	
		5. 6.	-25/7/ 1 60.
		A STATE OF THE STA	
SIGNED Man white	FILED AT EN	GINEER'S OFFICE	
INSPECTOR FOR CI			

16.38-35

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

THE PREMISES BEING LOT NO. 11411-11401 , HOUSE NO. WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

6955

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.