Nº 6964

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED		LOCATION FROM				
HOUSE NO. 1706						
SIZE OF PIPE USED C" L	DISTANCE FROM DOWN STREAM CURB LINE AND		18 cm	n Stream	14	8
WAS LATERAL AT CURB? Yes		in the source we	ng Hawaisa Ng Agalasa Sh	Name of the American		
WAS ATTACHED TO MAIN	- NAME OF CON	ITRACTOR		REML.	EY	
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL	OF BUILDING SE	RVED.			
			and discount for all successions to employ	7	S'du	No N
	+			12/2	-5 dup	
SIGNED Part Yalk	tan	FU FD AT FN	GINEER'S OFF	ICE	< 1;	3'
INSPECTOR FOR C						

16-74-13

office of the director of public service 6964 PERMIT TO TAP SEWER

	MASSILLON, OHIO, 1 lenembers 10 19
RECEIVED OF ALPHA	1. Henlu- FEE OF 5_20
	1 me 19
TO TAP	SEWER ON THE MARTIN
Land the second of the second	TYPE OF STREET
	, HOUSE NO. 170 6
	NANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	人名英格兰姓氏 医克里克氏 医克里克氏征 电流电流 医二氏性 医二氏性 网络亚洲 经收益的 医外侧线 医抗毒素
Name of Contractor	
가게 하다 하나 하나 가게 하는 사람들이 되었다.	

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.