## Nº 6974

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

date inspected $3-2.59$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2719		
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH 2/2 West of MH 245	<u>7</u>
WAS LATERAL AT CURB? YES	그는 그를 가득을 가는 말할까요? 등을 가는 생활한 가를 통해 그것을 가고 들지 않는 것을 그 것도 하는 것은 그를 가는 것이다.	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR QQ Dano	
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.	
	28/	
	25.	
SIGNED Not Vattorno Y INSPECTOR FOR CIT REMARKS M @ 22 57	FILED AT ENGINEER'S OFFICE	
REMARKS		

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE Nº 6974 PERMIT TO TAP SEWER

		<u>- Mau 20</u> 19
RECEIVED OF	Idleaux	FEE OF 5
	Ralens I Por	
	SEWER ON THE	17 E 7 F E 14 E 15 E 15 E 15 E 16 E 16 E 16 E 16 E 16
and a contract the second of the contract of t	AVE. ST. TYPE OF STREET	n on valent na 190 o len kanolika Perana kenologia haka kelo Daga Arbaba Koroliga Nasa.
PREMISES BEING LOT NO.	Ol. 262 , HOUSE NO	2419
. 보고의 무료들은 무리 만들게 될 때	: WITH ORDINANCE No. 2323, DULY P.	

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.