

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

2-24-59

HOUSE NO.

601

611

WAS LATERAL AT CURB?

 $y = 5$

WAS ATTACHED TO MAIN

No

NAME OF CONTRACTOR

R. Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



N

SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

16-35

3-28-59

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 6979

PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/29 19

RECEIVED OF

R. Ramsey

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

J. P. Roth

TO TAP

J. P. Roth

SEWER ON THE

A.

OF

Albion St E

AVE.

ST. TYPE OF STREET

ditch

THE PREMISES BEING LOT NO.

11508

HOUSE NO.

601

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL,
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R. Ramsey

Note This permit covers work outside of building only. Any work in
 walls of building is subject to Massillon Board of Health Regulations.