

No. 6992

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-5-59

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 811


SIZE OF PIPE USED 6" ^{UP} DISTANCE FROM FIRST MANHOLE
~~DOWN~~ STREAM TO DITCH AT

WAS LATERAL AT CURB? Yes ^{PROP.} CURB LINE AND DEPTH 86' from DEAD END M. N. 9

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR R. Marks

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Lathorn
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

16-50

3-28-59

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 6992

PERMIT TO TAP SEWER

7

MASSILLON, OHIO,

3-4-

19

RECEIVED OF

Roscoe Marks

FEE OF \$

5.00

FOR WHICH PERMISSION IS GRANTED

410 W. Beckwith

TO TAP

San.

SEWER ON THE

West

OF

Woodrow NE

AVE.

ST. TYPE OF STREET

11th

THE PREMISES BEING LOT NO.

Lot # 2 Colonial Hills

HOUSE NO.

811

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Roscoe Marks

Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.

Beckwith
*in S.W.E.**Col. Hill's**Marks*