Nº 6993

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 3-5-59 | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM |
|--|---|
| HOUSE NO. 918 | |
| SIZE OF PIPE USED 6// WAS LATERAL AT CURB? VS5 | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 220 NovTHOS NHO WESE CURB LINE AND DEPTH 220 |
| WAS ATTACHED TO MAIN | NAME OF CONTRACTOR HOLDING |
| SHOW BY DIAGRAM RELATION OF LATER | AL TO WALL OF BUILDING SERVED. |
| | |
| | |
| | |
| 순지를 필요했다면 다른 그를 받아 있 | |
| | |
| Rul of the | 70. 2220 |
| SIGNED (1) (X A) VONO INSPECTOR FOR CITY REMARKS | FILED AT ENGINEER'S OFFICE |

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| | en Agrico de Caración de Massillo. | Section 1 | ch 1/ 19 |
|------------------------------|--|--|---------------------|
| | MASSILLO | | |
| RECEIVED OF | Monney Unt | | FEE OF \$ |
| | | 777. | |
| FOR WHICH PERMISSION IS GRA | NTED Some Standard St | the state of the s | |
| | SEWER ON THE | | |
| TO TAP | | | |
| of | AVE. TYPE OF STREE | T Lared | - windre |
| | 3302-09 | | 918 |
| THE PREMISES BEING LOT NO | | _, HOUSE NO | 7/3 |
| | 본 경인 이렇게 통하게 하고 말했다. | | |
| WORK TO BE DONE IN ACCOR | DANCE WITH ORDINANCE No. 23 | 323, DULY PASSED E | Y THE CITY COUNCIL, |
| RULES OF THE DEPARTMENT O | F PUBLIC SERVICE. | | |
| | The state of the state of | | |
| \$4.Heid <u>d ceell</u> a oo | Alexa Ch | bear | |
| NAME OF CONTRACTOR | | | |

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.