

Nº 6994

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 2-26-59

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

TAPPED 118' EAST of MH @ 31

HOUSE NO. 226

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN Yes


NAME OF CONTRACTOR

R Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N
↑

Tremont



SIGNED

Roy Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

Relay
X

3-28-57

B. 11

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 6994

PERMIT TO TAP SEWER

Relay

MASSILLON, OHIO, 3-7-59 19.

Lurch
andRECEIVED OF Ray. Rensley FEE OF \$ 2⁰⁰

FOR WHICH PERMISSION IS GRANTED St. Anthony Church

TO TAP S.W. SEWER ON THE east

OF Shively & Thomas SE AVE. ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 1015 H, HOUSE NO. 226

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Ray. Rensley

Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.