Nº 7000

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-11-59	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	LAT IN	DEAD END MH S.
HOUSE NO. 2166	전통, 그런 보호를 통해 통해 함께 하지 않는다. 그 없는 것 같은 사람들은 사람들이 되었다. 그 사람		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB? NO			
WAS ATTACHED TO MAIN YES		9-1	· V Joe
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVE	ED. (/	
는 하는 그 사람들은 보고 함께 보는 하는 것이 되었다. 그는 것이 되는 것이 없는 것이다. 그는 것이 없는 것이 없는 것 			
		7	
		20	
보통하는 항상 등학자 보이 생활되는 보통 이 경기도 본 수입했다. 역 기업은 전문자 전 전기 기업을 받는 기계 되는 것 같은 기업을			1798
를 본 것을 가게 되는 것은 통일이 하는 중요 같은 모임. 400 - 12일 본 100 - 100 - 100 를 기다.			1.840
			⟨-32'-6 }
SIGNED KOY VITTAM	FILED AT ENGIN	EER'S OFFICE_	
/ INSPECTOR FOR CITY			
REMARKS	가 있다는 경기가 발생하다가 하고 있었습니다. 작업을 하는 것이 생물을 된 것으로 보고 있었습니다.		

Nº 7000

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Massillon, Ohio, $\frac{3}{19}$
RECEIVED OF FEE OF S 2
FOR WHICH PERMISSION IS GRANTED 1+ 1 13 1 1 2
TO TAP SEWER ON THE
of he of Day) nu Ave. Type of STREET des de
THE PREMISES BEING LOT NO. 11909 House No. 2/6/
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR ALGO V XISO

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.