Nº 7014

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-22-59 HOUSE NO. 70/	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	TEASTOR IST NA EAST OF L
SIZE OF PIPE USED 671	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? VPS	o di sul Eligio di Sulla in matanghi yaman in Tan	
WAS ATTACHED TO MAIN/V O	NAME OF CONTRACTOR	Maliban
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED	
		707 CC 70000
SIGNED Roy Hathan	FILED AT ENGINE	ER'S OFFICE
TEMARKS		

Nº 7014

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF CANA		April 16 19
RECEIVED OF	F. MADLOV	FEE OF \$
DR WHICH PERMISSION IS GRANTED	- Clibring Ad	may a state of
of the state of t	SEWER ON THE	
1 2 4 9.6	AVE. SI TYPE OF STREET	at
TE PREMISES BEING LOT NO. 1/3.		엄마 남자 그는 집 집 집에 그 집에 가장 하셨다.
ORK TO BE DONE IN ACCORDANCE WITH	ORDINANCE No. 2323, DUI	LY PASSED BY THE CITY COUNCIL
ULES OF THE DEPARTMENT OF PUBLIC SE	化二氯化甲基甲基苯甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基	
	invice.	

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.