

Nº 7018

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-22-59

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1923

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 40' NORTH OF MH @ SHAW 7.

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR R Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

MEASUREMENT 40' NOT 33' FROM MH @ SHAW

5-12-01
No 7018

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

April 22 19

RECEIVED OF

Ray Remy

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Robert German

TO TAP

saw

SEWER ON THE

west

OF

Ambler Rd NE

AVE.

ST. TYPE OF STREET

paved

THE PREMISES BEING LOT NO.

8557-8556

HOUSE NO.

1923

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Ray Remy

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.