

N<sup>o</sup> 7029

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-5-59

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

15-8' N/O WINDOW 9'D

HOUSE NO. 622

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

WAS LATERAL AT CURB? NO


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Joe V. Jones

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N ——— I



SIGNED

Ray Latham  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

JUL 14 1959

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

✓ N<sup>o</sup> 7029

## PERMIT TO TAP SEWER

MASSILLON, OHIO, May 6 19RECEIVED OF Joe L. JoeFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED Mr. S. P. AllenTO TAP San.SEWER ON THE EastOF Cornell St. NW. AVE.ST. TYPE OF STREET WestTHE PREMISES BEING LOT NO. 11921HOUSE NO. 622

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Joe L. Joe

Note This permit covers work outside of building only. Any work in  
walls of building is subject to Massillon Board of Health Regulations.