Nº 7032

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-7-59	IF SO HOW AND LOCATION FROM 1 1 203 SauTH of MH on T	- YUN
HOUSE NO. 764		
SIZE OF PIPE USED [11	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? NO	en en stagen i se en en en en sitte en tre en en en en se stagen per en	
WAS ATTACHED TO MAIN Y - 5	- NAME OF CONTRACTOR . Jose YOU	
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	
	18' Kubeep	
N — —	0 203 n' 8'h 0e"	0
and the control of th	0 203 n 1 8h	٠.
SIGNED ROY Vate	FILED AT ENGINEER'S OFFICE	
/ INSPECTOR FOR C	ITY	
REMARKS		

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Nº 7032

Massillon, Ohio, Mary 6	_19
RECEIVED OF LOS LOS FEE OF 5	
FOR WHICH PERMISSION IS GRANTED 71. V A Blaze	
TO TAP SEWER ON THE LACK	<u> </u>
OF CANALLY A. D.W. ST. TYPE OF STREET Auch	
THE PREMISES BEING LOT NO. 11934 , HOUSE NO. 704	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUN	NCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR AND A	

Note This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.