Nº 7033

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

·	· · · · · · · · · · · · · · · · · · ·		است
DATE INSPECTED 5 - 7 - 5 - 9	IF SO HOW AND LOCATION FROM TAPPED 88 5	MITHORMA	8 D
HOUSE NO. 726			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	•	
WAS LATERAL AT CURB? NO	land the second of the second		*.
WAS ATTACHED TO MAIN Y とう	NAME OF CONTRACTOR	YOu	
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	9'1	
	W.	18'	
La Company	781	48	
	tapped	1/6/200	
	and in the contribution of the second of the		
SIGNED Pour Lottas	FILED AT ENGINEER'S OFFICE		:
INSPECTOR FOR CIT			
REMARKS			1.0

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Nº 7033

MASSILLON, OHIO, May 6 19
RECEIVED OF FEE OF 5
FOR WHICH PERMISSION IS GRANTED 171 L Delice
TOR WINDOW PERMISSION IS GRANTED
TO TAP SEWER ON THE
OF CANULY St. TI.W. AVE. TYPE OF STREET AUCH
THE PREMISES BEING LOT NO. 11925 HOUSE NO. 120
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
Rules of the Department of Public Service.

NAME OF CONTRACTOR LAC LAC

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.