Nº 7037

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-173-19	FIRST MANHOLE DOWN STREAM TOP 22 SOUTH OS HA WINST
HOUSE NO. 625	
SIZE OF PIPE USED 611	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 100	
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR Sore Vine
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	-N (C) 222 0
	TAP
SIGNED Roy fathe	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 7037

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, Mess 6 19
RECEIVED OF Lee FEE OF \$ Z
FOR WHICH PERMISSION IS GRANTED 71 F. J. Bldr.
TO TAP DEW. SEWER ON THE LINETS
of County St. M.W. AVE. TYPE OF STREET Aut
그리는 어느 선생님은 사람들이 되었다. 그는 사람들은 사람들은 사람들이 가지를 가지 않는데 살아 없었다.
THE PREMISES BEING LOT NO. 11920, HOUSE NO. 625
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
Name of Contractor AC Lac

Note This permit cover's work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.