Nº 7038

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-19-5-9 IF SO HOW AND LOCATION FROM THE FIRST MANHOLE DOWN STREAM THE	P30'NORTHOS 3RONH From L.
HOUSE NO. 939	
SIZE OF PIPE USED C DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? N6	
WAS ATTACHED TO MAIN YS NAME OF CONTRACTOR	A Diona
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVE	D.
	17'
	J'n'orro
30	タルフルログキャ
SIGNED Roy Hathern	TAP
FILED AT ENGINE / INSPECTOR FOR CITY REMARKS	ERRS OFFICE

Nº 7038

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MAI	SSILLON, OHIO, 777411 14 19
RECEIVED OF CARCILLO	
OR WHICH PERMISSION IS GRANTED ACTUAL	
O TAP AMIL. SEWER C	
of 32 200 77.60 AVE. TYPE OF	- STREET MAYA SURFAIC
HE PREMISES BEING LOT NO. PT 11. 21.2	, HOUSE NO. 939
VORK TO BE DONE IN ACCORDANCE WITH ORDINANCE	No. 2323, DULY PASSED BY THE CITY COUNCIL
PULES OF THE DEPARTMENT OF PUBLIC SERVICE.	
IAME OF CONTRACTOR A. J. MILLI	4
Note This sessit fewers work outs	ide of building only. Any would in

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.