N^{o} 7043

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM |
|-------------------------------|---|
| HOUSE NO. | |
| SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH |
| WAS LATERAL AT CURB? | |
| WAS ATTACHED TO MAIN | NAME OF CONTRACTOR |
| SHOW BY DIAGRAM RELATION OF L | ATERAL TO WALL OF BUILDING SERVED. |
| | |
| SIGNED INSPECTOR FO | FILED AT ENGINEER'S OFFICE |
| DEMARKS | |

Nº 7043

PERMIT TO TAP SEWER

| | MASSILLON, OHIO, Brand 15 |
|-------------------|--|
| | MASSILLON, OHIO, |
| Ş | RECEIVED OF THE SELECT SEE OF S |
| M | FOR WHICH PERMISSION IS GRANTED 71 L S. Bler |
| (1) 100 8 | |
| | TO TAP SEWER ON THE TO TAKE |
| 1020 | of Junilly M.W. ST Type of Street doct |
| L'ave | THE PREMISES BEING LOT NO. 11907, HOUSE NO. 2150 |
| | WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL |
| | |
| | RULES OF THE DEPARTMENT OF PUBLIC SERVICE. |
| * : | |
| No. of the second | |
| | NAME OF CONTRACTOR FRIE L |
| | |
| | Note This permit covers work outside of building only. Any work in |

walls of building is subject to Massillon Board of Health Regulations.