Nº 7047

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-20-59	IF SO HOW AND LOCATION FROM
HOUSE NO. 2/53	FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH 190 WEST OF MY MY OFF CARVE
WAS LATERAL AT CURB? NO	CORB LINE AND DEPTH 770 UPSTO 1 1977 1774 6 THAT CARVE
WAS ATTACHED TO MAIN / 5	NAME OF CONTRACTOR Jac V Car
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.
	12', 1'
	0 190 90 89
	The state of the s
SIGNED NOT VATRONING	FILED AT ENGINEER'S OFFICE 1-7-60
REMARKS	

## Nº 7047

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Massitton, Ohio,
	RECEIVED OF 11, L. A. Bldg.) FEE OF 5
	FOR WHICH PERMISSION IS GRANTED 11. A. B.C.C.
-	TO TAP LAND SEWER ON THE
	OF Warishaw M.M. STE TYPE OF STREET
	THE PREMISES BEING LOT NO. 1/9// , HOUSE NO. 2/53
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
	NAME OF CONTRACTOR
	Note This permit covers work outside of building only. Any work in

walls of building is subject to Massillon Board of Health Regulations.