

Nº 7050

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-22-59

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM STUB IN MH 7' DEEP

HOUSE NO. 2133

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Joe V. Jones

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Satham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 1-7-60

REMARKS _____

Nº 7050

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO.

May 18

19

RECEIVED OF

M & A Blum

FEE OF \$

2

FOR WHICH PERMISSION IS GRANTED

M & A Blum

TO TAP

San

SEWER ON THE

South

OF

Windsor N.W.

AVE.
ST.

TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

11914

HOUSE NO.

2133

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Joe & Joe

Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.