## Nº 7063

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED $6-25-59$ HOUSE NO. $428$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH  / SOUTH OF MH  / Deep	$\bigcirc$
WAS LATERAL AT CURBY YES		
WAS ATTACHED TO MAIN NO SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	<u> </u>
	SIDE WALK	-
	- I EAST CLORE - 11' - SAN. SEWER - R7'DEEP WEST CLORE	-
SIGNED ROY HOTHOUN VINSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE	<del></del>

## Nº 7063

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Massillon, O	HIO, BOREZ	23 19
RECEIVED OF No.	my That	er med	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	1.1. 6	as kinned	
TO TAP Ann	SEWER ON THE	2 de et	
or_ 26 th 11. 70. W.	AVE. ST. TYPE OF STREET	And A	
THE PREMISES BEING LOT NO.	87, <sub>н</sub>	OUSE NO.	8
WORK TO BE DONE IN ACCORDANCE WITH		, DULY PASSED BY TI	IE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SER	/ICE,	,	

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.