$N^{o}$  7064

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-19-59	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH  SI SARTAT MARKET  R Drepo	
WAS LATERAL AT CURB?	· · · · · · · · · · · · · · · · · · ·	
	NAME OF CONTRACTOR 36, Myban	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	7/0297	
	80°°° 22' 1	
SIGNED Por attack	FILED AT ENGINEER'S OFFICE	
REMARKS		

## Nº 7064

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO, 1704	73 19
1/		
RECEIVED OF	The hand	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	Mountains	
		. /
TO TAPSEW	ER ON THE	<u> 70 — —                                 </u>
OF Standard Fig. 77 & AVE. TYP	e of Street. Cit	
THE PREMISES BEING LOT NO. 11945	, HOUSE NO,	<u> 20                                   </u>
WORK TO BE DONE IN ACCORDANCE WITH ORDINAL	NCE No. 2323, DULY PASSED BY	THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.		
Marie The rest	The bear	<i>i</i> .

Note This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.