## $N^{\circ}$ 7070

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	FIRST MANHOLE DOWN STREAM LATIN DEAD END MA 8 DE
HOUSE NO. 200/	
SIZE OF PIPE USED 6/	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NA	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR J. Halan
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	Though the state of the state o
	10 10 10 10 10 10 10 10 10 10 10 10 10 1
No.	
SIGNED PARTIES OF SOR COL	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CIT	Tagina to a take the tage of the contract of t
REMARKS	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF STAND SEWER ON THE STANDS BEING LOT NO. 300 / MOREY TO BE DONE IN ACCORDANCE WITH OPDINANCE NO. 2323 DILLY PASSED BY THE CITY COLINGIA

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Harry Chile

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.