

N^o 7072

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-15-59

IF SO HOW AND LOCATION FROM "Y" 34' SOUTH of 1ST Mth SOUT
FIRST MANHOLE DOWN STREAM OFF

HOUSE NO. 1041

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR R. Smarke

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED



SIGNED Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

6-40-01 1-50

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

No 7072

MASSILLON, OHIO, June 11 1919

RECEIVED OF James M. Mark FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED Frank Phillips

TO TAP San SEWER ON THE West

OF 23rd W.W. AVE. TYPE OF STREET High

THE PREMISES BEING LOT NO. 11989, HOUSE NO. 641

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR James M. Mark

Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.