

Nº 7096

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 7-12-59

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1315

SIZE OF PIPE USED 16"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 9' 6 1/2' Deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR J. M. Miller

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Ray Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

1-5-6

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 7096

PERMIT TO TAP SEWER

MASSILLON, OHIO,

July 16 1919

RECEIVED OF

Alvin M. Ward & Son

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

San

SEWER ON THE

East

OF

2nd St E

AVE.

ST. TYPE OF STREET

Hard surf.

THE PREMISES BEING LOT NO.

11964

HOUSE NO.

1315

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Harry B. Urban

Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.