Nº 7104

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM
HOUSE NO. 2925	FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH THE PROPERTY OF THE
WAS LATERAL AT CURB? // 5	(2) (2) (2) (2) (2) (2) (2) (2) (2) (3) (3) (3) (3) (4) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR G Name
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	AN QU'
	GARAGE
	The state of the s
7	A STATE OF THE STA
	2.
and the second of the second o	
SIGNED Mon & Mik	HU FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CIT	
REMARKS	

18,59

Nº 7104

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, 18 19
RECEIVED OF FEE OF 5 0 -
FOR WHICH PERMISSION IS GRANTED RATED THE THE THE PERMISSION IS GRANTED RATED THE THE PERMISSION IS GRANTED RATED THE PERMISSI
TO TAP RAUL. SEWER ON THE SAUTH
OF Challed 11 10 AVE. TYPE OF STREET ALLA
THE PREMISES BEING LOT NO. 3835-3836 , HOUSE NO. 21/25

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

AME OF CONTRACTOR A LUANA

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.