

No. 7111

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-31-59

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 711

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 201'

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR N. Urban

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Nathan
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

7-2-59
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 7111

PERMIT TO TAP SEWER

MASSILLON, OHIO,

July 31

19

RECEIVED OF

George Heston

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

side

SEWER ON THE

west

OF

Randolph Ave

AVE.

ST. TYPE OF STREET

West

THE PREMISES BEING LOT NO.

11406

HOUSE NO.

711

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL.
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Harry E. Urban

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.