


17.57

N^o 7123

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4/15/60IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 72'HOUSE NO. 809SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTHWAS LATERAL AT CURB? NOWAS ATTACHED TO MAIN YESNAME OF CONTRACTOR JOE Y JOE

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N SIGNED William E. Schind

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 12.2.60REMARKS THIS ONE HAD NO WYE SO WE TOOK OUT PIPE AND PUT IN A WYE

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 7123

PERMIT TO TAP SEWER

MASSILLON, OHIO,

8/10

19

RECEIVED OF

N + A Bedas

FEE OF \$ *2.00*

FOR WHICH PERMISSION IS GRANTED

Same

TO TAP

San

SEWER ON THE

W.

OF

Standish Circle

AVE

TYPE OF STREET

Driv

THE PREMISES BEING LOT NO.

~~12032~~ 12119

HOUSE NO.

809

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Joe d Joe

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.