

Nº 7124

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

SIZE OF PIPE USED _____

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

*No house built on this lot.
Refund*

SIGNED _____

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Refused

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 7124

PERMIT TO TAP SEWER

No house

MASSILLON, OHIO.

8/10

19

RECEIVED OF

N + A Bedus

FEE OF \$ 2⁰⁰

FOR WHICH PERMISSION IS GRANTED

same

TO TAP

San

SEWER ON THE

W.

OF

Standish Cir NW

AVE
ST

TYPE OF STREET

drift

THE PREMISES BEING LOT NO.

12031

HOUSE NO.

819

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Joe & Joe

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.