## Nº 7126

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	DATE INSPECTED 1-28-60 IF SO HOW AND LOCATION FROM 68 SOLTHOYD-ADENOISE
	HOUSE NO. 825 DISTANCE FROM FIRST MANHOLE
	SIZE OF PIPE USED DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
	WAS LATERAL AT CURB? Not and the second of t
	WAS ATTACHED TO MAIN YOU NAME OF CONTRACTOR YOU TO SOLVE
1	SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
v	
	We see the second of the secon
	16,00.40 F
	SIGNED FILED AT ENGINEER'S OFFICE
	REMARKS

## Nº 7126

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,
∪ <b>4</b>	RECEIVED OF Not Aldro FEE OF \$ 2100
IW.	TO TAPSEWER ON THE
	of tanded Cir Must. Type of STREET derd
	THE PREMISES BEING LOT NO. 1211 HOUSE NO. 825
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL

NAME OF CONTRACTOR JAC + HAL

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.