

11.5

Nº 7128

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 10-23-59.

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

STOR IN ATL on 4/19/76 6' deep

HOUSE NO. 835

SIZE OF PIPE USED 2"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN ✓ 45

NAME OF CONTRACTOR Bay View

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Nathan

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

12.2.60

REMARKS _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 7128

PERMIT TO TAP SEWER

MASSILLON, OHIO,

8/10

19

RECEIVED OF

N. A. Bede

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Same

TO TAP

San

SEWER ON THE

W

OF

Standish Ave No

AVE.
ST.

TYPE OF STREET

driv

THE PREMISES BEING LOT NO.

12028

HOUSE NO.

835

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Joe & Joe

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.