Nº 7134

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-11-5-9	IF SO HOW AND LOCATION FROM TAP 46 41.05 2ND 14-41.05 CN1
HOUSE NO. 2/60	FIRST MANHOLE DOWN STREAM 71- 01.01 2 7/1-01.731 C/91
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 10	
WAS ATTACHED TO MAIN X	NAME OF CONTRACTOR JOSEV Class
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
· · · · · · · · · · · · · · · · · · ·	19
	70
	V13'0 TAPWI SADDLEGE
SIGNED POUT TO INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE
BEMARKS	o Parka de Maria (1964), Maria (1964), a la calenda de la calenda de 1974. La calenda de la calenda de

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 7134

PERMIT TO TAP SEWER

	Massillon, Ohio,_	8/10 44 2000 19.
*	RECEIVED OF 12 4 Beden	FEE OF 5 2 U.C.
	FOR WHICH PERMISSION IS GRANTED Auma	
	TO TAP Land SEWER ON THE	77
	THE PREMISES BEING LOT NO. 12027, HOUSE	derik No. 2160
	THE PREMISES/SEING LOT NO.	NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.