FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

n de la companya de
DATE INSPECTED 9-8-89 IF SO HOW AND LOCATION FROM W 40 No. of 13T MWESTOR
HOUSE NO
SIZE OF PIPE USED DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBI NO
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
181 180
Marian Ma
90' (15'
SIGNED POLICY FILED AT ENGINEER'S OFFICE
REMARKS

Nº 7138

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N_{0}	-	71	38

PERMIT TO TAP, SEWER

Massillon, Ohio, 19
RECEIVED OF A A BULLA FEE OF 5 2 140
FOR WHICH PERMISSION IS GRANTED
TO TAP SEWER ON THE
of Machlanier MII) AVE. TYPE OF STREET dist
THE PREMISES BEING LOT NO. 120/8 HOUSE NO. 2/24
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL

NAME OF CONTRACTOR

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.