Nº 7139

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	FIRST MANHOLE DOWN STREAM STUBINM 6/2 0 4
HOUSE NO. 2/20	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBI	and the second of the second o
WAS ATTACHED TO MAIN 1/95	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATI	ERAL TO WALL OF BUILDING SERVED.
	A Réviosep
kan da abiya terma ka ka ka waxaya ka	
	- CLES STURIN
	(US-d 95%
SIGNED Ray Lathe	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR C	
REMARKS	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

, 159	Massillon, Ohio,
Bedro	RECEIVED OF 14 A BLAKA FEE OF \$2 160
<i>a</i>)	FOR WHICH PERMISSION IS GRANTED from e.
9	TO TAP SEWER ON THE
	of Marilon Marker Type of STREET dist
	THE PREMISES BEING LOT NO. 12017 , HOUSE NO. 2/20
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
	α
	NAME OF CONTRACTOR LICE T ALL

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.