Nº 7166

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED _ / - 5 - G.M.	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH  84 D:		
WAS LATERAL AT CURB? VES	and the second of the second o		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR PROPERTY		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
and the second the second and an experience of the second	1 K11/210-213		
	— W		
and a community of the appearance of a significant	45° B' NO. 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
$p \cdot U \cdot J$			
SIGNED NO A MAG	FILED AT ENGINEER'S OFFICE		
REMARKS			

## Nº 7166

## PERMIT TO TAP SEWER

and the second s		Massillon, Ohio, 10/1/1		
4	RECEIVED OF			
	FOR WHICH PERMISSION IS GRANTED 100	ER ON THE		
	Annual and the second section of the section of the second section of the s	OF STREET		
	THE PREMISES BEING LOT NO.	, HOUSE NO. 5/9		
	WORK TO BE DONE IN ACCORDANCE WITH ORDINAN RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	K TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL ES OF THE DEPARTMENT OF PUBLIC SERVICE.		

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.