Nº 7176

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-5-59	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO30/	
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 38' 8'D CURB LINE AND DEPTH
WAS LATERAL AT CURB? YES	and the second of the second o
WAS ATTACHED TO MAIN	NAME OF CONTRACTORH. URBAN
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
en de la composition de la composition La composition de la composition de la La composition de la composition della composition della composition della composition della composition de la composition de la composition de la composition de la composition della com	7'0 ***
	and the second control of the second control
	PROP LIME
	FLOW
SIGNED William E. Othe	J'k
INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE
REMARKS	and the common that the common of the common

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, 219

RECEIVED OF FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP SEWER ON THE

OF SEE TYPE OF STREET

THE PREMISES BEING LOT NO. HOUSE NO. 2323, DULY PASSED BY THE CITY COUNCIL

NAME OF CONTRACTOR HAVE CARE

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.