## No. 7178 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-9-5-9	IF SO HOW AND LOCATION FROM 109' 8' 8	
HOUSE NO		
SIZE OF PIPE USED6	DISTANCE FROM FIRST MANHOLE.  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	
WAS LATERAL AT CURB?NO	and the control of the control of the control of the second of the control of the	
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR R.G. MHRKS	
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	
	41 8 8 50	
ing the trackers with the control of	N . The second of the second o	
SIGNED William E. Mail	709' 12' C	

## Nº 7178

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO, 7/11/9-1957
RECEIVED OF KANAL ()	Marks FEE OF \$ 200
	ca. Portegas
TO TAP	WER ON THE
	PE OF STREET hard juntace
	HOUSE NO. 1732

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

AME OF CONTRACTOR & BUCKLE 4. FRANKS

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.