# Nº 7182

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12-22-	FIRST MANHOLE DOWN STREAM
HOUSE NO. 865	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH // 5 / D / P
WAS LATERAL AT CURB? / P	5
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR A MANAGEMENT
SHOW BY DIAGRAM RELATION OF I	LATERAL TO WALL OF BUILDING SERVED.
	10 / E7 / De
er all vitable had been a large and	and the contract of the first production of the contract of th
N	who have a distributed and resolved a source of the source
•	
SIGNED PAGE INSPECTOR FO	FILED AT ENGINEER'S OFFICE

#### OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 7182

### PERMIT TO TAP SEWER

	10/
	Massillon, Ohio, $\frac{12}{2}$
	RECEIVED OF A (12 le 1) FEE OF \$2
:.	FOR WHICH PERMISSION IS GRANTED (1000 p.)
	Por Which Parking to the Control of
	TO TAP SEWER ON THE
7	of the bland & AVE. TYPE OF STREET
:	THE PREMISES BEING LOT NO. 9737 , HOUSE NO. 8/5
	A 2222 PMV DISCEPTION OF COMME
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
	ROLES OF THE BELLANIALITY OF T GOLD OF THE SELECTION OF T
	NAME OF CONTRACTOR H. Who

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.