

Nº 7185

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 12-31-59

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 742

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR R. Penley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

Relay Repair

3-23-24
2-11-60

Relay

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 7185

PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/8 1960

RECEIVED OF *D. Remy* FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED *Shirley W. Anderson*

TO TAP *from* SEWER ON THE *N.Y.*

OF *Rutledge NE* AVE. TYPE OF STREET *Hard surf*

THE PREMISES BEING LOT NO. *3986*, HOUSE NO. *7112*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Remy*

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.