

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
DATE, TIME AND SIGNED WHEN RETURNED

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 84' - 18" FROM UPSTREAM MT.

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR: P. G. MARKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

W. L. & White

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

17-13
5-16-60

NOTES: IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, MASSILLON, OHIO.

NO. 7229

PERMIT TO TAP SEWER

MASSILLON, OHIO, May 5 1960

RECEIVED OF

R. G. Marks

FEE OF \$

5.00

FOR WHICH PERMISSION IS GRANTED

Russell Miller

TO TAP

San

SEWER ON THE

West

OF

25th St. N.W.

AVE.

ST. TYPE OF STREET

Dist

THE PREMISES BEING LOT NO.

7079-7080

HOUSE NO.

557

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R. G. Marks

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.