Nº 7246

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-7-60	. IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 16+6	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 185 E, 6 F AH 9 Dee
WAS LATERAL AT CURBI	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR RAPAS
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
	45° 0 = 100 ×
19 Land Committee Committe	and the second of the second o
	3° 8en 2 / (1)
SIGNED NOW NOW AND THE PARTY NAMED IN COLUMN TO THE PARTY NAMED IN COLUMN	FILED AT ENGINEER'S OFFICE
/INSPECTOR FOR CI	Literatura de la completa de la comp
REMARKS	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO. Juli 6 19
RECEIVED OF RACIOL MANKS FEE OF \$ 500
FOR WHICH PERMISSION IS GRANTED 6 9. STUMES
TO TAPSEWER ON THE
OF BUTTERN D. W AVE. TYPE OF STREET MALL SILL GAS
THE PREMISES BEING LOT NO. 14 16
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323 DULY PASSED BY THE CITY COUNCIL

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR AREA MARKE

Note This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.