Nº 7259 AND SIGNED WHEN RETURNED FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

DATE INSPECTED 7/7/60	IF SO HOW AND LOCATION FROM 62'-80
HOUSE NO. 1620	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	the substitution of the second
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR A. S. Deans
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
· · · · · · · · · · · · · · · · · · ·	N
entropie (Normania esperante) Transport	MAN POHOSE
	61' - 4' K
SIGNED William E. Mill	FILED AT ENGINEER'S OFFICE 12 2-60
INSPECTOR FOR CE	

Nº 7259

PERMIT TO TAP SEWER

٠.	
	MASSILLON, OHIO, Quality - 19
	RECEIVED OF A CALLA FEE OF \$ 50C
	TO TAP SEWER ON THE CRAT
	OF 11-44 ST. TYPE OF STREET Dist
	THE PREMISES BEING LOT NO. # 74 12098 HOUSE NO. 1670
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
	RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
	NAME OF CONTRACTOR A DIGINAL

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.