Nº 7267

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7/6/60	IF SO HOW AND LOCATION FROM 101'-7'D FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? No	The state of the s
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR A. J. Duna
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	32
	N
and a subject to the subject of the	76
SIGNED William E. Mit	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CIT	
REMARKS	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE Nº 7267 PERMIT TO TAP SEWER

Market Company of the	ASSILLON, OHIO, 15
RECEIVED OF	FEE OF \$
FOR WHICH PERMISSION IS GRANTED Tandard	Hausing Cont
TO TAPSEWER	d Z
TO TAPSEWER	R ON THE
OF 167/ F AVE. TYPE	of street dert
THE PREMISES BEING LOT NO. = 17/06	, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC	E No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR (1.) Diana	·
Note This permit covers work ou	tside of building only. Any work in

walls of building is subject to Massillon Board of Health Regulations.